

# 66-F-219-C  
W.P. # 20-60  
HWY. # 7 &  
ST. MARY'S  
BY-PASS  
C.N.R. OVERHEAD





66 F 219 C

H. Q. GOLDER & ASSOCIATES LTD.

CONSULTING CIVIL ENGINEERS  
HEAD OFFICE - TORONTO, ONTARIO

H. Q. GOLDER  
V. MILLIGAN  
L. G. SODERMAN  
J. L. SEYCHUK

747 HYDE PARK ROAD  
LONDON, ONTARIO  
471-9600

June 8, 1967.

Department of Highways,  
Materials and Testing Division,  
Hwy. 401 and Keele St.,  
DOWNSVIEW, Ontario.

ATTENTION: Mr. A. G. Stermac, P.Eng.

RE: Soils Investigation  
Proposed Hwy. 7, St. Marys  
(WP 26/60) /66


Dear Sirs:

Since completion of the subsurface investigation at the above site, the soil samples have been stored in our London laboratory.

We shall be disposing of these samples at the end of June 1967, and if you have further use for them, please contact our office or arrange to have them picked up at our office before this date.

Yours truly,

H. Q. GOLDER & ASSOCIATES LTD.,



Brian E. W. Dowse, P. Eng.

BEWD:cmm  
66514

*H. Q. Golder*

Mr. A. P. Watt,  
Regional Bridge Location Engr.,  
Bridge Section,  
Regional Office (London).

Foundation Section,  
Materials & Testing Div.,  
Room 107, Lab. Bldg.

December 14, 1966

C.N.R. Overhead (St. Mary's Bypass) -  
Hwy. No. 7 - District No. 3 (Stratford)

-- W.P. 20-60 --

---

We have reviewed Preliminary Plan D 6071-Pl  
for the above mentioned structure.

The designer appears to have complied with  
the recommendations given to Mr. M. Gvildys by  
Mr. A. G. Stermac, by 'phone on November 16, 1966.

*H. G. Selby*

KGS/MdeF

K. G. Selby,  
SUPERVISING FOUNDATION ENGR.  
For:  
A. G. Stermac,  
PRINCIPAL FOUNDATION ENGR.

cc: Foundations Office ✓  
Gen. Files

MEMORANDUM

To: Mr. A. G. Stermac  
Principal Foundation Engineer  
Lab Building  
D O W N S V I E W

FROM: A. P. Watt

DATE: November 30, 1966

OUR FILE REF.

IN REPLY TO

---

SUBJECT: W.P. 20-60, Bridge Site 19-454,  
C.N.R. Overhead (St. Mary's Bypass),  
3.0 miles west of Hwy. 19,  
Highway 7,  
District 3, Stratford.

---

Attached please find one copy of the preliminary plan D-6071-P1 for the above noted structure.

Would you kindly review the bridge foundations proposed and inform me if they are satisfactory.

A reply would be appreciated within the next two weeks.



A. P. WATT  
REGIONAL BRIDGE LOCATION ENGINEER

APW:gf  
ATT'D

NOTE

W.P. 20-60

November 16, 1966

Mr. M. Guildis advised that deep foundations represent serious construction problems because of proximity of railway tracks.

Asked whether piles can be used instead.

Yes. Tube piles are suggested and it is believed that practical refusal will be met at around elevation 1050.

Practical refusal:

Delmag<sup>G</sup> D-22 5 blows/inch for the last 1-2 feet penetration.

A. G. Stermac

P.S.

Footings can be kept at a depth sufficient for frost protection.

Mr. B. S. Davis,  
Bridge Engineer,  
Bridge Division.

Foundation Section,  
Materials & Testing Div.,  
Room 107, Lab. Bldg.

Attention: Mr. S. McCombie

October 4, 1966

OCT - 4 1966

FOUNDATION INVESTIGATION REPORT FOR D.H.O.  
BY: H. Q. Golder and Associates, Limited -  
Proposed C.N.R. Overhead, Highway No. 7,  
St. Mary's, Ontario -- District 3 (Stratford)

-- W.P. 20-60 --

Attached, please find the above mentioned report prepared and submitted by the consultant, H. Q. Golder and Associates Ltd.

We have reviewed the report and have found the factual information adequate and well presented. Regarding the foundations, we would recommend a slight change in the consultant's recommendations. We feel that the foundation elevation could be 2 - 3 ft. higher - i.e., 1062 to 1063. The west footings could be higher than the East ones. This slight change will decrease somewhat the excavation depth, making the work easier and more economical.

We believe that you will now have enough information to proceed with your design work. Should you, however, have any additional questions or problems that you would like to discuss, please feel free to contact this Office.

AGS/adsP

Attach.

cc: Messrs. B. S. Davis (2)  
H. A. Ireganek  
D. W. Farran  
A. Gater  
A. P. Watt  
J. C. Tillcock  
J. Roy  
A. Watt

Foundations Office  
Len. Files

*Althorn*  
A. G. Sternas,  
PRINCIPAL FOUNDATION ENGINEER

REVISED NOVEMBER, 1967

## BRIDGE INSPECTION REPORT

SUFFICIENCY RATING \_\_\_\_\_ INDEX NO. Middlesex - 454HIGHWAY NO. 7 DISTRICT NO. 3 COUNTY )  
DISTRICT) MiddlesexNUMBER AND NAME OF STRUCTURE C.N.R. OverheadTYPE OF STRUCTURE Three span semi-continuous prestressed concrete beamsINSPECTED BY C. Rahn DATE OF INSPECTION April - 19 70MILEAGE FROM 5.0 miles West of East Entrance to St. Mary'sBRIDGE DIMENSIONS \_\_\_\_\_ BRIDGE PLAN NO. D6071SPAN 35' - 45' - 35' LENGTH OF BRIDGE 116'-6"WIDTH OF BRIDGE ROADWAY 40' WIDTH OF BRIDGE 46'CLEARANCE \_\_\_\_\_ DATE OF CONSTRUCTION 1968

## APPROACH GEOMETRICS

Structure on crest vertical curve and straight alignment.

## WATERWAY ADEQUACY

N/A

## CONDITION OF BRIDGE

RETURN TO D.H.O.  
 BRIDGE MAINTENANCE  
 SECTION

## ABUTMENTS

Reinforced concrete - good

## BALLAST WALLS

Reinforced concrete - good

## PIERS

Two three column reinforced concrete with reinforced concrete caps - good

## BEARINGS

 $\frac{3}{4}$ " neoprene pads - good

## MAIN GIRDERS, TRUSSES OR RIBS

Prestressed concrete beams - semi-continuous

## FLOOR BEAMS

Nil. Reinforced concrete diaphragms only - good

19-454

DEPARTMENT OF HIGHWAYS ONTARIO

MEMORANDUM

To: Mr. W. D. Birch,  
Bridge Maintenance and Inspection  
Engineer - Maintenance Office,  
Admin. Bldg.

From: Foundation Section,  
Materials & Testing Office,  
Room 107, Lab. Bldg.

ATTENTION: Mr. H. W. C. Rahn      DATE: May 19, 1970

OUR FILE REF.      IN REPLY TO

SUBJECT: C.N.R. Overhead (St. Mary's Bypass)  
Hwy. 7, Site Index Middlesex - 454,  
District No. 3 (Stratford).

With respect to your memorandum of May 13, 1970, to Mr. A. Rutka, Materials and Testing Engineer, Attention: Mr. G. A. Wrong, Principal Soils Engineer, we wish to advise you of the following:

On May 20, 1969, the undersigned discussed the distress signs, which have appeared at the above mentioned crossing, with Mr. J. McKeown from the Regional Materials Office.

Attached is a photostat copy of the note of this telephone discussion, which we believe is self-explanatory.

We do not know whether any remedial or maintenance measures were carried out after the mentioned discussion. We would suggest that you contact Mr. J. McKeown and obtain from him, all the available records and information.

Should you wish to discuss this matter further, please feel free to contact this office.

AGS/MdeF  
Attach.

*A. G. Stermac*  
A. G. Stermac  
PRINCIPAL FOUNDATION ENGINEER

cc: Mr. G. A. Wrong  
Foundations Files  
Gen. Files

Note - *Passover ground under slab*  
*WFB*  
*June - 2 '70*

May 20th, 1969

C.N.R. Overhead (St. Mary's Bypass  
Hwy. 7, District 3, W.P. 20-60

Note:

Telephone conversation with Jack McKeown, London-Mat. and Testing

Approach fills have settled, there is a 2½" void under approach slabs. Curb is pulling away from the slab. There is a tension crack at the end of approach slab where it meets the pavement. Jack has carried out a number of borings within the fill area where problems have occurred. Under 31" of granular a layer of soft clay was formed ( $U_L = 30.6\%$   $e_L = 14.2\%$   $P_L = 16.4$   $W = 15.8\%$ ) which varied in thickness from about 3 ft. to 7 ft. It has a consistency that with little effort it can be squeezed through the fingers. Below this soft layer the fill is firm to hard. It can hardly be drilled with the power auger.

Conclusion

It is obvious that the upper part of the approach fills was not built as specified. The material is too wet and consequently settles. It will probably settle even more once it is exposed to highway traffic. A failure could not be completely ruled out.

The very best remedial measure would be to remove and replace this material with a properly compacted fill placed at **opt.** moisture content. All else will be only temporary and long lasting maintenance measures have to be reckoned with.

A.G. Stermac

C.V.R. O'Leary (St. Mary's Bypass  
Highy 7. District 3; W.P. 20-60.

May 20th 1967

Note:

Telephone conversation with Jack Luskow  
London - Mat & Esting.

Approach fills have settled, there is a  $2\frac{1}{2}$ " void  
under approach slabs. Curbs is pulling away  
from the slabs. There is a tension crack at the  
end of approach slabs where it meets the  
pavement.

Jack has carried out a number of borings  
within the fill area where problems have  
occurred. Under 31" of granular a layer  
of soft clay was found ( $L_1 = 30.6\%$ ,  $P_2 = 14.2\%$ ,  
 $P_1 = 16.4$ ,  $w = 15.8\%$ ) which varied in thickness  
from about 3 ft to 7 ft. It has a consistency  
that with little effort it can be squeezed  
through the fingers. Below this soft layer the  
fill is firm to hard. It can hardly be drilled  
with the rocer auger.

### Conclusion

It is obvious that the upper part of the approach  
fills was not built as specified. The material  
is too wet and consequently settles. It will  
probably settle even more once it is exposed to  
highway traffic. A failure could not be  
completely ruled out.

The very best remedial measure would be to remove and replace this material with a properly compacted fill based at an moisture content. All else will be only temporary and long lasting maintenance measures have to be reckoned with.

W. J. ...

11 copies  
from files  
from files

DEFECTS IN NEGATIVE DUE TO  
CONDITION OF ORIGINAL DOCUMENT

Mr. A. Rutka,  
Materials & Testing Engineer,  
Downview.

Bridge Maintenance Section  
B.M.C. Rahn,  
for W.D. Birch.

Mr. C.L. Strong,  
Principal Soils Engineer.

May 13, 1970.

Re: C.M.S. Overhead (St. Mary's Bypass), Highway 7  
Site Index Middlesex-454, District 3, Stratford

It was noted during a recent inspection of the subject structure, that settlement voids and erosion undermining have occurred under the concrete approach slabs at each abutment. Settlement of the slabs was also evident. Pavement on the west approach fill adjacent to the structure was recently patched, in a longitudinal fissure of up to eighteen inches wide, to the north of the highway centre line. The fissure is upwards of twenty feet in length. The structure was constructed in 1968.

Please arrange for the necessary tests and studies of the site, which will enable us to determine what, if any, corrective measures may be undertaken to avoid failure of the approaches and approach slabs.

B.M.C. Rahn,  
for W.D. Birch,  
Bridge Maintenance and Inspection Engineer.

H.C.S./ma  
c.c. A.J. Orr  
T.K. Murphy

RETURN TO D.H.O.  
BRIDGE MAINTENANCE  
SECTION

DEFECTS IN NEGATIVE DUE TO  
CONDITION OF ORIGINAL DOCUMENT

STRINGERS

Nil

DECK

Reinforced concrete - good

WEARING SURFACE

Nil - deck surface only

EXPANSION JOINTS

Rodofoam, styrofoam, hot poured paraplastic

HANDRAIL POSTS

Aluminum parapet rail posts, reinforced concrete end posts

HANDRAILS

Reinforced concrete parapet wall  
Two lines galvanized pipe rail

WINGWALLS

Reinforced concrete - good

CURBS

Reinforced concrete - good

SIDEWALKS

Nil

DRAINAGE

Structure self draining on vertical curve

RETAINING WALLS

Nil

EMBANKMENT SLOPES

Steep seeded granular slopes

SUPER IMPOSED DOCUMENT MAY  
APPEAR AS MULTI-FEED ON FILM.

---

ADDITIONAL OBSERVATIONS

1. Approach slabs settled and undermining.
2. Approach pavement badly cracked and breaking up.
3. Considerable collected gravel on deck along curbs.

---

GENERAL CONDITION OF STRUCTURE

Good

---

STRUCTURAL STRENGTH

---

DESIGN LOAD

HS 20-44

---

PRESENT POSTING

None

---

OVERLOAD PERMIT

---

RECOMMENDATIONS

1. Clear deck of debris.
2. Recommendation concerning approaches will be made following a study by Materials and Testing as requested in memo of May 13, 1970. - *SEE May 19 '70.*
3. *Pressure grout under slab*

DATE \_\_\_\_\_ 196 \_\_\_\_\_

SIGNATURE \_\_\_\_\_

DEPARTMENT OF HIGHWAYS ONTARIO

MEMORANDUM

To: Mr. W. D. Birch,  
Bridge Maintenance and Inspection  
Engineer - Maintenance Office,  
Admin. Bldg.

FROM: Foundation Section,  
Materials & Testing Office,  
Room 107, Lab. Bldg.

ATTENTION: Mr. H. W. C. Rahn

DATE: May 19, 1970

OUR FILE REF.

IN REPLY TO

SUBJECT: C.N.R. Overhead (St. Mary's Bypass)  
Hwy. 7, Site Index Middlesex - 454,  
District No. 3 (Stratford).

With respect to your memorandum of May 13, 1970, to Mr. A. Rutka, Materials and Testing Engineer, Attention: Mr. G. A. Wrong, Principal Soils Engineer, we wish to advise you of the following:

On May 20, 1969, the undersigned discussed the distress signs, which have appeared at the above mentioned crossing, with Mr. J. McKeown from the Regional Materials Office.

Attached is a photostat copy of the note of this telephone discussion, which we believe is self-explanatory.

We do not know whether any remedial or maintenance measures were carried out after the mentioned discussion. We would suggest that you contact Mr. J. McKeown and obtain from him, all the available records and information.

Should you wish to discuss this matter further, please feel free to contact this office.

AGS/MieF  
Attach.

*A. G. Stermac*  
A. G. Stermac  
PRINCIPAL FOUNDATION ENGINEER

cc: Mr. G. A. Wrong  
Foundations Files  
Gen. Files

## MEMORANDUM

TO: Mr. A. Rutka,  
Materials & Testing Engineer,  
Downsview.

FROM: Bridge Maintenance Section  
H.W.C. Rahn,  
for W.D. Birch.

ATTENTION: Mr. G.A. Wrong,  
Principal Soils Engineer.

DATE: May 13, 1970.

OUR FILE REF. IN REPLY TO

SUBJECT: Re: C.N.R. Overhead (St. Mary's Bypass), Highway 7  
Site Index Middlesex-454, District 3, Stratford

It was noted during a recent inspection of the subject structure, that settlement voids and erosion undermining have occurred under the concrete approach slabs at each abutment. Settlement of the slabs was also evident. Pavement on the west approach fill adjacent to the structure was recently patched, in a longitudinal fissure of up to eighteen inches wide, to the north of the highway centre line. The fissure is upwards of twenty feet in length. The structure was constructed in 1968.

Please arrange for the necessary tests and studies of the site, which will enable us to determine what, if any, corrective measures may be undertaken to avoid failure of the approaches and approach slabs.

  
H.W.C. Rahn,  
for W.D. Birch,  
Bridge Maintenance and Inspection Engineer.

HWCR/■  
c.c. E.J. Orr  
T.W. Murphy

C. N. R. O'head (St. Mary's Bypass  
Hwy 7. District 3; W.P. 20-60.

May 20th 1969

Note:

Telephone conversation with Jack Lockwood  
London-Heat & Testing.

Approach fills have settled, there is a  $2\frac{1}{2}$ " void under approach slabs. Curbs is pulling away from the slabs. There is a tension crack at the end of approach slab where it meets the pavement.

Jack has carried out a number of borings within the fill area where problems have occurred. Under 31" of granular a layer of soft clay was found ( $L_c = 30.6\%$   $P_c = 14.2\%$   $P_1 = 16.4$   $W = 15.8\%$ ) which varied in thickness from about 3 ft to 7 ft. It has a consistency that with little effort it can be squeezed through the fingers. Below this soft layer the fill is firm to hard. It can hardly be drilled with the power auger.

#### Conclusion

It is obvious that the upper part of the approach fills was not built as specified. The material is too wet and consequently settles. It will probably settle even more once it is exposed to highway traffic. A failure could not be completely ruled out.

The very best remedial measure would be to remove and replace this material with a properly compacted fill placed at opt. moisture content. All else will be only temporary and long lasting; <sup>maintenance</sup> ~~essential~~ measures have to be reckoned with.

Afternoon

2 copies  
from files  
from files

LT TO ST. CLAY CLAY TILL

Sept. 1968 Approach Slab

① 31" 3-4 part material

31" - 9 1/2'

9 1/2' - 12'

LT clay stiff

w 12.5%

30.2 - 13.7

att. L<sup>c</sup> 30.6 PL 14.2%  
16.4

w = 15.8 11.5%

② Center of

31 - 5' soft material

④ 30' from BH 1

⑤ 132'

③ 31 - 5' w. soft

East End

⑥ Bed pond at  
1/2

2 1/2" void

McKeown

JAEL McKeown

ST MARY'S C.N.R O'HEAD

MAY 1969.

66-F-219C

**H. Q. GOLDER & ASSOCIATES LTD.**

**CONSULTING CIVIL ENGINEERS  
HEAD OFFICE - TORONTO, ONTARIO**

**747 HYDE PARK ROAD  
LONDON, ONTARIO  
471-9600**

**H. Q. GOLDER  
V. MILLIGAN  
L. G. SODERMAN  
J. L. SEYCHUK**

W.P. 20 - 60

REPORT

TO

DEPARTMENT OF HIGHWAYS, ONTARIO

ON

SOIL CONDITIONS AND FOUNDATIONS

PROPOSED CANADIAN NATIONAL RAILWAY CROSSING  
PROPOSED HIGHWAY NO. 7 - LINE 'A'

ST. MARY'S

ONTARIO

**Distribution:**

11 copies - Department of Highways, Ontario,  
Toronto, Ontario

2 copies - H. Q. Golder & Associates Ltd.,  
London, Ontario

September, 1966

66514

## TABLE OF CONTENTS

	<u>Page</u>
ABSTRACT	1
INTRODUCTION	2
PROCEDURE	2
SITE AND GEOLOGY	4
SUBSOIL CONDITIONS	4
GROUND-WATER CONDITIONS	6
DISCUSSION	
General	7
Foundations	7
Excavations	9
Approach Embankments	9
Groundwater	10
ABBREVIATIONS	In Order Following Page 10
RECORDS OF BOREHOLES	
FIGURES 1	- Boring Plan and Soil Stratigraphy Section
2-5	- Grain Size Distribution Curves

## ABSTRACT

The results of an investigation to determine the subsurface conditions at the site of the proposed grade separation of the proposed Highway No. 7, Line 'A', and the Canadian National Railway, St. Mary's, Ontario are reported. Recommendations are made for the foundation design of the proposed structure and approach embankments.

It was found that the site is underlain by glacial till. The upper 5 to 6 feet of the till consists of a light brown silty clay. Below this level the till is a grey silt with zones of stratified silt and of sand. Groundwater was found to be within a few feet of the ground surface.

It is recommended that the abutments and the piers be founded on spread footings on the grey till at or below elevation 1060 with an allowable bearing pressure of 4 tons per square foot. The embankments may be constructed to full height in one stage providing the recommendations are followed. The groundwater may be controlled by pumping from sumps.

## INTRODUCTION

H. Q. Golder & Associates Ltd have been retained by the Department of Highways, Ontario, to carry out a soil investigation at the site of the proposed grade separation at the Canadian National Railway on proposed Highway No 7, Line 'A', for the proposed St. Mary's Bypass, Ontario. The purpose of the investigation was to determine the sub-soil and ground-water conditions at the proposed pier and abutment locations and to make recommendations for foundation design and the construction of the approach embankments.

## PROCEDURE

The field work for this investigation was carried out between September 9 and 14, 1966. A total of 4 boreholes, one accompanied by a dynamic cone penetration test and 4 additional cone penetration tests were put down using a skid-mounted diamond drillrig supplied and operated by the F. E. Johnston Drilling Company Ltd. The borings which were generally put down in BX casing size, penetrated to depths ranging from 16 to 34 feet. The cone tests were driven to refusal at shallower depths.

The ground-water level at the site was observed during drilling and for two weeks after completion of the investigation by readings taken in the piezometer and standpipes installed in the borings. The field work was supervised throughout by an engineer from our staff.

A detailed log for each of the borings and dynamic cone penetration tests is given in the Record of Borehole and the Record of Penetration Test sheets following the text of this report. The locations of the borings carried out during this investigation, together with a section of the inferred soil stratigraphy along the centre line of the proposed crossing, are shown in Figure 1.

Samples obtained during the investigation were returned to our laboratory for detailed examination and testing. The results of the laboratory tests are shown on the Records of Boreholes and on Figures 2 to 5, inclusive.

The elevations given in this report are referred to the top of track elevation on the centre line of the existing road where it crosses the Canadian National Railway line. The elevation of the top of track at this point was given as 1078.13, referred to geodetic datum, on the Department of Highways, Ontario, Plan E-3991-1.

## SITE AND GEOLOGY

The present gravel road along which it is proposed to relocate Highway No. 7 follows the boundary between the counties of Middlesex and Perth. The road presently crosses the Canadian National Railway track on a level crossing where the railway embankment is raised some 10 feet above the surrounding rolling land.

The major soil type found in this part of Ontario is glacial till overlying bedrock. The glacial till interbedded with outwash deposits underlies the site to a depth of 40-50 feet as observed in the St. Mary's Cement Company's quarry located just north of the site. The bedrock in the area is limestone of the Delaware formation.

## SUBSOIL CONDITIONS

The detailed stratigraphy encountered in the 4 boreholes and inferred in the penetration tests is shown on the Record of Boreholes and the Record of Penetration Test sheets. The stratigraphy interpolated from this data is presented on Figure 1. The soil conditions at the site may be summarized in the following manner.

Each borehole encountered 1 to 2 feet of loose sand or gravel fill overlying the original topsoil. The fill forms the edge of the embankment that carries the present county road over the level crossing.

The predominant stratum at the site is glacial till which is a stiff light brown silty clay with traces of sand and gravel for the upper 5 to 6 feet and in the major stratum is a very dense grey silt with some fine and coarse gravel and with a trace of clay. The upper and the lower tills show considerable localized zoning with layers and pockets of stratified silts and of sands which have possibly been laid down and subsequently enveloped in the till during minor retreats and re-advances of the ice front during advance of the ice sheets.

Standard Penetration Tests carried out in the upper clayey till stratum and reported on the Records of Boreholes give 'N' values that range from 6 to 37 with an average value of 23. The liquid limit of this stratum was measured as 23 per cent and the natural water content ranged from 18.3 to 22.9 per cent with an average value of 21.0 per cent. The grain size distribution curves for samples tested from this stratum are presented in Figure 2.

The lower till is basically a very dense grey silt with sub-angular gravel throughout and a trace of clay. The pockets of sands and silts can be as great as 3 feet thick and vary in colour from brown to light grey. Standard Penetration tests carried out in the grey till give 'N' values that are generally greater than 100 except in two pockets where the values were 28. The measured liquid limit of this stratum varied from non-plastic to 26.3 per cent with an average value of 23.0 per cent and the natural water content ranged from 11.3 per cent to 15.8 per cent with an average value of 12.5 per cent. Grain size distribution curves for samples tested at various depths in the grey till are presented in Figure 3. Grain size distribution curves for samples tested from the silt and from the sand zones are presented in Figures 4 and 5 respectively.

#### GROUND-WATER CONDITIONS

One piezometer and 4 standpipes were installed in the boreholes and sealed as sketched on the Records of Boreholes. Readings taken up to two weeks after completion of drilling showed the groundwater to have stabilized at

between elevation 1069 to 1070 in the standpipes and elevation 1064 in the piezometer that was sealed into the lower till. Observations of the water level in the well, located near the southeast corner of the crossing and marked on Figure 1, showed that when it was pumped out to approximately elevation 1055 it took almost 24 hours to come back up to its original level of approximately elevation of 1065. No artesian water pressure was encountered at the site.

## DISCUSSION

### General

It is understood that the proposed Canadian National Railway crossing is to be a triple-span structure, each span being 45 feet long. The proposed highway grade is to be approximately elevation 1107 necessitating roadway approach embankments as high as 39 feet above the surrounding land.

### Foundations

The abutments and piers of the bridge may be safely founded on the very dense grey silty till with an allowable bearing pressure of 4 tons per square foot at or below elevation 1060. The settlement of the bridge founded as recommended should be negligible. Excavations for the

abutments and piers should be carried out in the dry to prevent softening of the subsoil. It is recommended that, in order to prevent softening of the subsoil at founding elevation due to surface water construction operations, the base of the excavations should be immediately covered by a thin working mat of lean concrete as soon as foundation grade is reached.

If retaining type abutments are used, it is recommended that free-draining and non-frost susceptible granular backfill be used behind the abutments. The granular backfill should be compacted in horizontal thin layers and should extend horizontally from the back face of the abutment walls for a minimum distance of 6 feet. A maximum loose layer of 18 inches may be used providing vibratory equipment is used for compaction. It is recommended that, providing there is effective drainage behind the walls, a co-efficient of earth pressure at rest,  $K_0$ , of 0.4 and a total unit weight,  $\gamma$ , of 135 lb./cu.ft. be used for the compacted granular backfill in the design of the walls.

### Excavations

The excavations for the abutment and pier foundations shall be cut back to a natural slope and where restricted (i.e. close to the railway embankment) shall be supported to prevent loss of ground from under the railway tracks.

### Approach Embankments

The approach embankments may be safely constructed to their required height in one stage providing the top soil is removed where it exists before any fill is placed and providing the embankment is constructed of compacted fill, properly controlled in the field with a maximum side slope of 2 horizontal to 1 vertical. Material in the embankment should be compacted to 100 per cent of Standard Proctor maximum density under conditions of controlled water content.

The settlement of the embankments built as recommended should be small with the majority of the settlement taking place during construction.

Groundwater

It was noted during drilling that when the well was pumped out considerable time was required for it to refill; therefore it was concluded that the water seepage into the excavations will be minor, probably only from seams of sand or gravel, and can be simply and efficiently controlled during construction by pumping from sumps in the bottom of the excavations. It is anticipated that there will be no major ground-water construction problems.

*Brian E.W. Dowse*

B. E. W. Dowse, P.Eng.

*L. G. Soderman*

L. G. Soderman, P.Eng.

BEWD:mr

66514

30 September, 1966

## LIST OF ABBREVIATIONS

The abbreviations commonly employed on each "Record of Borehole," on the figures and in the text of the report, are as follows:

### I. SAMPLE TYPES

<i>AS</i>	auger sample
<i>CS</i>	chunk sample
<i>DO</i>	drive open
<i>DS</i>	Denison type sample
<i>FS</i>	foil sample
<i>RC</i>	rock core
<i>ST</i>	slotted tube
<i>TO</i>	thin-walled, open
<i>TP</i>	thin-walled, piston
<i>WS</i>	wash sample

### II. PENETRATION RESISTANCES

**Dynamic Penetration Resistance:** The number of blows by a 140-pound hammer dropped 30 inches required to drive a 2-inch diameter, 60 degree cone one foot, where the cone is attached to 'A' size drill rods and casing is not used.

**Standard Penetration Resistance, *N*:** The number of blows by a 140-pound hammer dropped 30 inches required to drive a 2-inch drive open sampler one foot.

<i>WH</i>	sampler advanced by static weight—weight, hammer
<i>PH</i>	sampler advanced by pressure—pressure, hydraulic
<i>PM</i>	sampler advanced by pressure—pressure, manual

### III. SOIL DESCRIPTION

#### (a) *Cohesionless Soils*

<i>Relative Density</i>	<i>N, blows/ft.</i>
Very loose	0 to 4
Loose	4 to 10
Compact	10 to 30
Dense	30 to 50
Very dense	over 50

#### (b) *Cohesive Soils*

<i>Consistency</i>	<i>c<sub>u</sub>, lb./sq. ft.</i>
Very soft	Less than 250
Soft	250 to 500
Firm	500 to 1,000
Stiff	1,000 to 2,000
Very stiff	2,000 to 4,000
Hard	over 4,000

### IV. SOIL TESTS

<i>C</i>	consolidation test
<i>H</i>	hydrometer analysis
<i>M</i>	sieve analysis
<i>MH</i>	combined analysis, sieve and hydrometer <sup>1</sup>
<i>Q</i>	undrained triaxial <sup>2</sup>
<i>R</i>	consolidated undrained triaxial <sup>2</sup>
<i>S</i>	drained triaxial
<i>U</i>	unconfined compression
<i>V</i>	field vane test

#### NOTES:

<sup>1</sup>Combined analyses when 5 to 95 per cent of the material passes the No. 200 sieve.

<sup>2</sup>Undrained triaxial tests in which pore pressures are measured are shown as  $\bar{Q}$  or  $\bar{R}$ .

## LIST OF SYMBOLS

### I. GENERAL

$\pi = 3.1416$   
 $e =$  base of natural logarithms 2.7183  
 $\log_e a$  or  $\ln a$ , natural logarithm of  $a$   
 $\log_{10} a$  or  $\log a$ , logarithm of  $a$  to base 10  
 $t$  time  
 $g$  acceleration due to gravity  
 $V$  volume  
 $W$  weight  
 $M$  moment  
 $F$  factor of safety

### II. STRESS AND STRAIN

$u$  pore pressure  
 $\sigma$  normal stress  
 $\sigma'$  normal effective stress ( $\bar{\sigma}$  is also used)  
 $\tau$  shear stress  
 $\epsilon$  linear strain  
 $\epsilon_{xy}$  shear strain  
 $\nu$  Poisson's ratio ( $\mu$  is also used)  
 $E$  modulus of linear deformation (Young's modulus)  
 $G$  modulus of shear deformation  
 $K$  modulus of compressibility  
 $\eta$  coefficient of viscosity

### III. SOIL PROPERTIES

#### (a) Unit weight

$\gamma$  unit weight of soil (bulk density)  
 $\gamma_s$  unit weight of solid particles  
 $\gamma_w$  unit weight of water  
 $\gamma_d$  unit dry weight of soil (dry density)  
 $\gamma'$  unit weight of submerged soil  
 $G_s$  specific gravity of solid particles  $G_s = \gamma_s / \gamma_w$   
 $e$  void ratio  
 $n$  porosity  
 $w$  water content  
 $S_r$  degree of saturation

#### (b) Consistency

$w_L$  liquid limit  
 $w_P$  plastic limit  
 $I_P$  plasticity index  
 $w_S$  shrinkage limit  
 $I_L$  liquidity index =  $(w - w_P) / I_P$   
 $I_C$  consistency index =  $(w_L - w) / I_P$   
 $e_{max}$  void ratio in loosest state  
 $e_{min}$  void ratio in densest state  
 $D_r$  relative density =  $(e_{max} - e) / (e_{max} - e_{min})$

#### (c) Permeability

$h$  hydraulic head or potential  
 $q$  rate of discharge  
 $v$  velocity of flow  
 $i$  hydraulic gradient  
 $k$  coefficient of permeability  
 $j$  seepage force per unit volume

#### (d) Consolidation (one-dimensional)

$m_v$  coefficient of volume change  
 $= -\Delta e / (1+e) \Delta \sigma'$   
 $C_c$  compression index =  $-\Delta e / \Delta \log_{10} \sigma'$   
 $c_s$  coefficient of consolidation  
 $T_v$  time factor =  $c_v / d^2$  ( $d$ , drainage path)  
 $U$  degree of consolidation

#### (e) Shear strength


$\tau_f$  shear strength  
 $c'$  effective cohesion  
 $\phi'$  effective angle of shearing resistance, or friction  
 $c_u$  apparent cohesion\*  
 $\phi_u$  apparent angle of shearing resistance, or friction  
 $\mu$  coefficient of friction  
 $S_f$  sensitivity

$\left. \begin{array}{l} \text{in terms of effective stress} \\ \tau_f = c' + \sigma' \tan \phi' \end{array} \right\}$   
 $\left. \begin{array}{l} \text{in terms of total stress} \\ \tau_f = c_u + \sigma \tan \phi_u \end{array} \right\}$

\*For the case of a saturated cohesive soil,  $\phi_u = 0$  and the undrained shear strength  $\tau_f = c_u$  is taken as half the undrained compressive strength.

# RECORD OF BOREHOLE 1

LOCATION **See Figure 1**      BORING DATE **SEPT. 9-12, 1966**      DATUM **GEODETIC**  
 BOREHOLE TYPE **WASH BORING**      BOREHOLE DIAMETER **BX CASING**  
 SAMPLER HAMMER WEIGHT **140 LB.** DROP **30 INCHES**      PEN. TEST HAMMER WEIGHT **140 LB.** DROP **30 INCHES**



VERTICAL SCALE  
1 INCH TO 5'-0"

GOLDER & ASSOCIATES

DRAWN JWA  
CHECKED JWA





# RECORD OF PEN. TESTS 5 & 6

LOCATION

See Figure 1

BORING DATE SEPT. 12, 1966


DATUM GEODETIC

BOREHOLE TYPE PENETRATION TESTS

BOREHOLE DIAMETER —

SAMPLER HAMMER WEIGHT — LB. DROP — INCHES

PEN. TEST HAMMER WEIGHT 140 LB. DROP 30 INCHES



15-0-5 Percent axial strain at failure

VERTICAL SCALE  
1 INCH TO 5'-0"

COLDER & ASSOCIATES

DRAWN LWA  
CHECKED JJA

# RECORD OF PEN. TESTS 7 & 8

LOCATION

See Figure 1

BORING DATE SEPT. 13-14, 1966


DATUM GEODETIC

BOREHOLE TYPE PENETRATION TESTS

BOREHOLE DIAMETER —

SAMPLER HAMMER WEIGHT — LB. DROP — INCHES

PEN. TEST HAMMER WEIGHT 140LB DROP 30 INCHES



VERTICAL SCALE  
1 INCH TO 5'-0"

GOLDER & ASSOCIATES


DRAWN J.W.A.  
CHECKED [Signature]

# GRAIN SIZE DISTRIBUTION

SILTY CLAY TILL

FIGURE 2

M.I.T. GRAIN SIZE SCALE




COBBLE SIZE	COARSE	MEDIUM	FINE	SAND SIZE	FINE	SILT SIZE	CLAY SIZE
	GRAVEL SIZE						

GOLDER & ASSOCIATES

# GRAIN SIZE DISTRIBUTION

SILT TILL

FIGURE 3




# GRAIN SIZE DISTRIBUTION

## SILT LAYER

FIGURE 4

M.I.T. GRAIN SIZE SCALE




COBBLE SIZE	COARSE	MEDIUM	FINE	COARSE	MEDIUM	FINE	SILT SIZE	CLAY SIZE
	GRAVEL SIZE			SAND SIZE			FINE GRAINED	

# GRAIN SIZE DISTRIBUTION SILTY SAND

FIGURE 5

M.I.T. GRAIN SIZE SCALE

SIZE OF OPENING - INS. U.S.S. SIEVE SIZE - MESHES / IN.



LEGEND  
B.H. SAMPLE ELEVATION  
+1 2 1035.4

COBBLE SIZE	GRAVEL SIZE	SAND SIZE			SILT SIZE	CLAY SIZE
		COARSE	MEDIUM	FINE		
					FINE GRAINED	